








Legenda degradari

Degradari finsaje

-  Interventii recente (tencuieli, cimentari, zugraveli)
-  Vegetatie, Biocidare
-  Eflorescenta de saruri
-  Ciobiri

Degradari zidarie

-  Mortar spalat
-  Fisuri si fracturi
-  Limita tronson 7

Degradari datorate interventiei omului

-  Consolidare cu beton aparent

Verificator Expert	Nume	Semnatura	Cerinta	Referat/Expertiza Nr./Data			
S.C. NITS S.R.L. J26-312-1999; CUI RO11766934 540074 Tg.Mures, str.Vulcan nr.9 tel 0744791303 e-mail nitsalexandru@gmail.com				Beneficiar:	Primaria Municipiului Sighisoara	Pr.nr:	251/2017
				Adresa:	545400 Sighisoara, Str. Piata Muzeului Nr. 7, Jud. Mures	Faza:	P.T.+D.E
				Titlu proiect:	Lucrari de consolidare si restaurare Zidul Cetatii Sighisoara- Tronsonul 7		
				Adresa:	Cetatea Sighisoara		
Sef proiect	arh. Nits A.		Sc. 1:50	Titlu plansa:		TRONSONUL 7 - SEGMENTUL 4 RELEVU DEGRADARI	
Relevat	arh. Adrian I. arh. Petrisor A.					Pl.nr:	A/6
Desenat	arh. Adrian I.		2019				